

LIST OF PLATES

Plate number		Page number
Chapter 2		
2.1	Sathanur dam	42
2.2	Pick-up dam	42
Chapter 4		
4.3.1	Hydro-electricity generation unit	106
Chapter 5		
5.1	Check dam to control soil erosion	128
Chapter 6		
6.1	Sathanur dam with water gushing down the spillways	142
6.2	Dam surroundings developed into a beautiful garden	142
6.3	Crocodile farm	144
6.4	Swimming pool	144
6.5	Ornamental fishes exhibition	145
Chapter 16		
16.1	Water logged field next to Thachampattu tank	471
16.2	Peraiyampattu branch canal in a dilapidated state	471
16.3	Weed infested Peraiyampattu tank	475
16.4	Thenkarimbalur branch canal	475
16.5	Sorry state of Agarampallipattu branch canal	476
16.6	Velayampakkam tank - weeds infested and a grazing ground for cattle	476
16.7	Status of the lined canal	479

16.8	Water from Thenmudiyar main canal being used for washing clothes	479
16.9	Cement slabs missing in Vanapuram canal	481
16.10	Canal mutilated by the villagers of Palayanur to divert more water towards one side	490
16.11	Hard to believe that the branch canal of Mangalam has been filled up for easy passage	490

Chapter 17

17.1.1	Eucalyptus plantation right across the Varagur tank	513
17.2.1	Kallakurichi Cooperative Sugar Mill	517
17.2.2	Sugar mill effluent released into the Ponnaiyar - a drinking water source for the natives of Melandhal	517