

## LIST OF TABLES

<i>Table</i>	<i>Page</i>
1. Some important properties of inorganic NLO materials	15
2. Some important properties of organic NLO materials	16
3. Some important properties of semiorganic NLO materials	17
4. Tilt angles ( $\delta$ ), FWHM of main peaks ( $W_m$ ) and FWHM of shoulder peaks ( $W_s$ ) of pure and impurity added ZTS single crystals	58
5. Vibrational band assignments of thiourea compared with its analogues.	76
6. Vibrational band assignments of pure and urea added ZTS crystals.	79
7. Vibrational band assignments of pure and Ni <sup>2+</sup> added ZTS crystals.	80
8. Vibrational band assignments of pure and Mg <sup>2+</sup> added ZTS crystals.	82
9. Lattice parameters (a, b and c) of pure and impurity added ZTS crystals	87
10. Lattice volumes, densities, lattice masses and impurity concentrations of pure and impurity added ZTS crystals. The AAS data are also added.	89
11. The Vicker's hardness numbers	94
12. The dielectric constants for urea added ZTS crystals along a- direction	110
13. The dielectric constants for urea added ZTS crystals along b- direction	110
14. The dielectric constants for urea added ZTS crystals along c- direction	111
15. The dielectric constants for Ni <sup>2+</sup> added ZTS crystals along a- direction	111
16. The dielectric constants for Ni <sup>2+</sup> added ZTS crystals along b- direction	112
17. The dielectric constants for Ni <sup>2+</sup> added ZTS crystals along c- direction	112
18. The dielectric constants for Mg <sup>2+</sup> added ZTS crystals along a- direction	113
19. The dielectric constants for Mg <sup>2+</sup> added ZTS crystals along b- direction	113
20. The dielectric constants for Mg <sup>2+</sup> added ZTS crystals along c- direction	114
21. The dielectric loss factors for urea added ZTS crystals along a- direction	118

22.	The dielectric loss factors for urea added ZTS crystals along b- direction	118
23.	The dielectric loss factors for urea added ZTS crystals along c- direction	119
24.	The dielectric loss factors for Ni <sup>2+</sup> added ZTS crystals along a- direction	119
25.	The dielectric loss factors for Ni <sup>2+</sup> added ZTS crystals along b- direction	120
26.	The dielectric loss factors for Ni <sup>2+</sup> added ZTS crystals along c- direction	120
27.	The dielectric loss factors for Mg <sup>2+</sup> added ZTS crystals along a- direction	121
28.	The dielectric loss factors for Mg <sup>2+</sup> added ZTS crystals along b- direction	121
29.	The dielectric loss factors for Mg <sup>2+</sup> added ZTS crystals along c- direction	122
30.	The AC electrical conductivities for urea added ZTS crystals along a- direction	126
31.	The AC electrical conductivities for urea added ZTS crystals along b- direction	126
32.	The AC electrical conductivities for urea added ZTS crystals along c- direction	127
33.	The AC electrical conductivities for Ni <sup>2+</sup> added ZTS crystals along a- direction	127
34.	The AC electrical conductivities for Ni <sup>2+</sup> added ZTS crystals along b- direction	128
35.	The AC electrical conductivities for Ni <sup>2+</sup> added ZTS crystals along c- direction	128
36.	The AC electrical conductivities for Mg <sup>2+</sup> added ZTS crystals along a- direction	129
37.	The AC electrical conductivities for Mg <sup>2+</sup> added ZTS crystals along b- direction	129
38.	The AC electrical conductivities for Mg <sup>2+</sup> added ZTS crystals along c- direction	130
39.	The $\epsilon_r$ , $\tan\delta$ and $\sigma_{ac}$ ( $\times 10^{-8}$ mho/m) values at 40°C for pure and impurity added ZTS crystals	134
40.	The AC activation energies	135