

LIST OF FIGURES

FIGURE No.	TITLE	PAGE No.
1.1	Beach Profile - Definition Sketch	4
1.2	Beach profiles - (A) Under Swell Condition (B) Under Storm Condition	6
1.3	Beach profiles : Storm and Swell Conditions	6
1.4	Onshore - Offshore Sediment Movement	10
1.5	Alongshore Sediment Transport on Beaches	10
1.6	Schematic Diagrams of Storm Wave Attack on Beach and Dune	12
1.7	NMP Layout Showing Existing and Proposed Facilities	18
1.8	Location Map of the Study Area	22
1.9	Annual Average Discharge for Netravati and Gurpur Rivers	24
1.10	Wave Characteristics Along Mangalore Coast (After Dattatri 1973)	26
1.11	Tide Curve - Mangalore Coast	26
1.12	Current Pattern Along the Indian Coast	26
1.13	Progress in Armoring Along Mangalore Coast	27
1.14	Seawall Under Construction at Sasihitulu	29
1.15	Breakwater Under Construction at Netravati- Gurpur River Mouth	30
2.1	Various Methods of Displaying Grain Size Distributions	34
3.1	Sampling Locations for Beach Face Sediments	50
3.2	Beach Face Sample Collection	51

FIGURE No.	TITLE	PAGE No.
3.3	Location 1 - Someshwar Temple (South Side of Rocky Outcrop)	51
3.4	Erosion, Transportation and Deposition for a Hypothetical Source (After McLaren 1981)	53
3.5	Log-probability Plot (A) Typical Plot (After Visher 1969) (B) For Location No.1	59
3.6	Design Details of Sea Sled	62
3.7	Sea Sled	63
3.8	Sea Sled Survey in Operation	63
3.9	Sea Bed Sediment Sample Locations (NMPT)	66
3.10	<i>In-situ</i> Sampling Locations - Pre-monsoon (07/05/2000)	68
3.11	<i>In-situ</i> Sampling Locations - Post-monsoon (21.11.1999)	69
3.12	Collection of <i>In-situ</i> Water Sample	74
4.1	STP Around Netravati-Gurpur River Mouth - November 1994	88
4.2	STP Around Netravati-Gurpur River Mouth - November 1997	89
4.3	STP Around Netravati-Gurpur River Mouth - November 1999	90
4.4	STP Around Netravati-Gurpur River Mouth - January 2000	91
4.5	STP Along Panambur and KREC Beach - November 1997	98
4.6	STP Along Panambur and KREC Beach - November 1999	99
4.7	STP Along Panambur and KREC Beach - January 2000	100

FIGURE No.	TITLE	PAGE No.
4.8	STP Around Mulky-Pavanje River Mouth - January 2000	103
4.9	STP Along Beach Profile at KBR	107
4.10	Beach Profiles at Ullal - Post-monsoon	111
4.11	Beach Profiles at Bengre - Post-monsoon	112
4.12	Layout and Surveying Details at Sasihitulu location	115
4.13	Beach Profiles at Sasihitulu - Pre-monsoon	116
4.14	Beach Profiles at Sasihitulu - Post-monsoon	117
4.15	Progress in Beach Recovery Process at Sasihitulu CPs	118
4.16	Beach Profiles at Sasihitulu - With and Without Seawalls	120
4.17	Beach Profiles at SCP ₈ - Before and After the Construction of Seawall	122
4.18	Beach Profiles at Sasihitulu - Effect of Monsoon Waves	123
4.19	Beach Profiles at Sasihitulu - With and Without Seawalls and Effect of Monsoon Waves	124
4.20	Beach Profiles at KREC Beach - With and Without Seawalls	126
4.21	Dry Beach Widths Along Ullal and Bengre Beach	128
4.22	Dry Beach Widths Along Thannirubhavi Beach	130
4.23	Dry Beach Widths Along Sasihitulu Beach	131
4.24	Seawall at Sasihitulu Location	132
4.25	Breakwaters at Netravati - Gurpur River Mouth	132
4.26	Sea Bed Contours Near NMP - Long-term Changes (A) 8 years (B) 30 years	137

FIGURE No.	TITLE	PAGE No.
4.27	Sea Bed Contours Near NMP - During and After I stage Breakwater Construction	139
4.28	Sea Bed Contours Near NMP - Before and After the Construction of Breakwaters	140
4.29	Sea Bed Contours Near NMP - Seasonal Changes	142
4.30	Sea Bed Contours Near NMP - After the Construction of Breakwaters	143
4.31	Northern side of Northern Breakwaters - NMP	145
4.32	Southern side of Southern Breakwaters - NMP	145
4.33	Percentage of Sand, Silt and Clay in Sea Bed Sediments	147
4.34	Temporal Variations of SSC Along Mangalore Coast - <i>In-situ</i> Data	153
4.35	Sediment Distribution Pattern Along Mangalore Coast from OCM Data	155
4.36	Scatter Plot - Measured vs Estimated SSC	156
4.37	Shoreline Changes Around Netravati-Gurpur River Mouth	158
4.38	Shoreline Changes Around Netravati-Gurpur River Mouth (1905 - 1968)	161
4.39	Shoreline Changes Around Mulky-Pavanje River Mouth	163